

GMAX™ II PC Board Kit 287516, 287648, 287649

3900/5900/5900HD/5900 Convertible/7900

LineLazer IV PC Board Kit 287689

3900/5900/200HS

311049 rev.D



Important Safety Instructions.


Read all warnings and instructions in this manual. Save these instructions.

CAUTION

Electrostatic discharges can damage components on PC board. Use a ground strap when handling or installing PC board.

Using configurations other than those listed results in poor sprayer performance.

- 1 Refer to your sprayer repair manual for the procedures.
- 2 Do **Pressure Relief Procedure**.
- 3 Remove pressure control cover.
- 4 Remove PC board.
- 5 Cut out and remove the resistor(s) on PC board according to figure and table.
- 6 Install PC board.
- 7 Install pressure control cover.



	3900				5900				7900				200 HS
	GMAX II 3900	3900 Striper	Intl GMAX II 3900	Intl 3900 Striper	GMAX II 5900	5900 Striper	5900 Convertible	Intl GMAX II 5900	Intl 5900 Striper	GMAX II 7900	Intl GMAX II 7900	200 HS Striper	Intl 200 HS Striper
1	X		X	X		X			X		X		X
2		X		X	X	X		X				X	X
3			X		X	X				X	X	X	X
4							X	X	X	X	X	X	X

PROVEN QUALITY. LEADING TECHNOLOGY.

Graco Information

TO PLACE AN ORDER, contact your Graco distributor, or call **1-800-690-2894** to identify the nearest distributor.

All written and visual data contained in this document reflects the latest product information available at the time of publication.
Graco reserves the right to make changes at any time without notice.

MM 311049

Graco Headquarters: Minneapolis
International Offices: China, Belgium, Japan, Korea
GRACO INC. P.O. BOX 1441 MINNEAPOLIS, MN 55440-1441

<http://www.graco.com>
PRINTED IN U.S.A. 311049
2/2005 Rev. 5/2006