

Parts Change Notice

Some parts in Rev. C of manual 308-456 have changed but have not yet been changed in the instruction manual. Please note the changes below and mark them in your manual or keep this sheet with your manual.

Assembly No.	Series Letter Change	Part That Changed	Ref No.	Part Description	Description of Change
Model 237-413	—	236-015	42	Optimiser HVLP Spray Gun	Replaced by Part No. 239-561 Delta HVLP Spray Gun, .070" orifice. See manual 308-741.



All written and visual data contained in this document reflects the latest product information available at the time of publication. Graco reserves the right to make changes at any time without notice.

June 10, 1998