

Parts Change Notice

Some parts in Rev. Orig. of manual 6 000 162 have changed but have not yet been changed in the instruction manual. Please note the changes below and mark them in your manual or keep this sheet with your manual.

VISCOUNT II SHOVEL PUMP

Model 6 720 035

Model 098 168

Assembly No.	Series Letter Change	Part That Changed	Ref. No.	Part Description	Description of Change
6 720 035	A	223-646	4	Viscount II Motor	Changed to 235-345.
098 168	A	223-646	15	Viscount II Motor	Changed to 235-345.

Page 12 :

TECHNICAL DATA

Model 6 720 035

Maximum Hydraulic Fluid Intake Pressure.....53 bar (780 psi)

Maximum Fluid Working Pressure170 bar (2500 psi)

Model 098 168

Maximum Hydraulic Fluid Intake Pressure.....70 bar (1000 psi)

Maximum Fluid Working Pressure217 bar (3200 psi)

